Oak Ridge Reservation
Quality Assurance Report
for Meteorological Towers
For Towers A, B, C, K, L, M, W, Y

Kevin R. Birdwell Computational Science and Engineering Division Oak Ridge National Laboratory

April 2010

Tower ID Summary:

Name	Alternate Names	ORR Site	Elevation (m)	Easting, Northing (m)	Measuring Hts
Tower A	MT4,7571	ORNL	263	743179,3978105	10,30
Tower B	MT3, 6555, 07	ORNL	256	743398,3979683	10,30
Tower C	MT2, 1057, 03	ORNL	261	741423,3978768	10,30,100
Tower K	MT1, 1208	ETTP	253	735675,3979503	10,60
Tower L	MT7, 1209	ETTP	233	735110,3978654	10,30
Tower M	MT10, 208A	ETTP	237	735720,3976860	10
Tower W	MT6, Y12W, West	Y12	326	748890,3986700	10,60
Tower Y	MT9, PSS Tower	Y12	290	747926.3985859	15, 33

Thursday, April 1, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, April 2, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1000-1045	96.0 96.0	Temp10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Record high temperature (86F) observed in Oak Ridge (previous record 84F)

Saturday, April 3, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name Stat	tus Time Range	% Data Recovered	Sensors Affected	Comments
		15-min 60-min		
Tower A ERI	R 1000-1845	64.0 64.0	Temp10	10m Temp values in error (sensor error?)
				Values corrected using interpolation / Tower C
Tower B OK	: -	100.0 100.0		
Tower C OK	- -	100.0 100.0		
Tower K OK	- -	100.0 100.0		
Tower L OK	- -	100.0 100.0		
Tower M OK	- -	100.0 100.0		
Tower W ERI	R 0215-1115	64.0 64.0	All	Missing data (Y12 network communication error)
Tower Y ERI	R 0215-1115	64.0 64.0	All	Missing data (Y12 network communication error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Cold front passage around 12 pm

Sunday, April 4, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, April 5, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1100-1545	79.0 79.0	Temp10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Oak Ridge (KOQT) Max. Temp of 87F tied record high for date

Tuesday, April 6, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1400-1945	75.0 75.0	Temp10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Oak Ridge (KOQT) Max. Temp of 87F set new record high for date

Wednesday, April 7, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	ERR	0900-1345, 1500-1545	75.0	75.0	Temp10	10m Temp values in error (sensor error?)
						Values corrected using interpolation / Tower C
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0530	99.0	100.0	All	Missing data (Y12 network communication error)
Tower Y	ERR	0530	99.0	100.0	All	Missing data (Y12 network communication error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, April 8, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thundershowers crossed area around 0900 hrs; cold front passage late morning-mid afternoon.

Friday, April 9, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1100-1145	96.0 96.0	Temp10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, April 10, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status T	ime Range		Recovered 60-min	Sensors A	ffected	Comments
Tower A	OK		100.0	100.0			
Tower B	OK		100.0	100.0			
Tower C	OK		100.0	100.0			
Tower K	OK		100.0	100.0			
Tower L	OK		100.0	100.0			
Tower M	OK		100.0	100.0			
Tower W	OK		100.0	100.0			
Tower Y	OK		100.0	100.0			

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Sunday, April 11, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, April 12, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	ERR	0800-1445	71.0 71.0	Temp 10	10m Temp values in error (sensor error?)
					Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	0745, 1100	98.0 100.0	All	Missing data (Y12 network communication error)
Tower Y	ERR	0745, 1100	98.0 100.0	All	Missing data (Y12 network communication error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, April 13, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308 Email <u>birdwellkr@ornl.gov</u>, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	0800-1245	59.0 59.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
	ERR	1300-1545	88.0 88.0	All	Power supply replaced at Tower A by Shaw Env.
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, April 14, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	0800-1145, 2100-2345	75.0 75.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		1000-W aviation lights replaced at 100-m level
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, April 15, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1500-1545	96.0 96.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	ERR	1500	99.0 100.0	All	Missing data (Y12 network error?)
Tower Y	ERR	1500	99.0 100.0	All	Missing data (Y12 network error?)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thundershowers/showers formed along eastern escarpment of Cumberland Plateau/Mtns. and drifted east bringing light showers to Norris / Central Anderson Co. around 1600 hrs. First observed pattern of this type for the year (which is typical of summer).

Friday, April 16, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1100-2000	60.0 60.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, April 17, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		Recovered 60-min	Sensors Affected	Comments
Tower A	ERR	1100-1800	68.0	68.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0745-2345	32.0	32.0	All	Missing data (Y12 communication failure)
Tower Y	ERR	0745-2345	32.0	32.0	All	Missing data (Y12 communication failure)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Cold front passage 0600-1200 hrs

Sunday, April 18, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308 Email <u>birdwellkr@ornl.gov</u>, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range		Recovered 60-min	Sensors Affected	Comments
Tower A	ERR	1100-1900	64.0	64.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0000-2300	4.0	4.0	All	Missing data (Y12 communication failure)
Tower Y	ERR	0000-1200	51.0	51.0	All	Missing data (Y12 communication failure)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, April 19, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	,	n Recovered 60-min	Sensors Affected	Comments
Tower A	ERR	1000-1045, 1200-1845	67.0	67.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	0345-0645, 0745, 1015	81.0	80.0	All	Missing data (Y12 communication failure)
Tower Y	ERR	0345-0645, 0745, 1015-1030	80.0	80.0	All	Missing data (Y12 communication failure)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, April 20, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	0400-1900	33.0 33.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Wednesday, April 21, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	ERR	1500-1845, 2100-2345	71.0 71.0	Temp 10	10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, April 22, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered 15-min 60-min	Sensors Affected
Tower A	ERR	1100-1245	13 mm 00 mm	Temp 10
	ERR	1400-1545	84.0 84.0	All
Tower B	OK		100.0 100.0	
Tower C	OK		100.0 100.0	
Tower K	OK		100.0 100.0	
Tower L	OK		100.0 100.0	
Tower M	OK		100.0 100.0	
Tower W	OK		100.0 100.0	
Tower Y	OK		100.0 100.0	

Comments

10m Temp values in error (sensor error?) Values corrected using interpolation / Tower C Site offline / Repairs to 10m temperature performed by Shaw Environmental.

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, April 23, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Saturday, April 24, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Heavy rain / thundershowers crossed ORR around 1900-2100 hrs.

Sunday, April 25, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Monday, April 26, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status Time Range	% Data Recovered 15-min 60-min	Sensors Affected	Comments
Tower A	OK	100.0 100.0		
Tower B	OK	100.0 100.0		
Tower C	OK	100.0 100.0		
Tower K	OK	100.0 100.0		
Tower L	OK	100.0 100.0		
Tower M	OK	100.0 100.0		
Tower W	OK	100.0 100.0		
Tower Y	OK	100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Tuesday, April 27, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data	Recovered	Sensors Affected	Comments
			15-min	60-min		
Tower A	OK		100.0	100.0		
Tower B	OK		100.0	100.0		
Tower C	OK		100.0	100.0		
Tower K	OK		100.0	100.0		
Tower L	OK		100.0	100.0		
Tower M	OK		100.0	100.0		
Tower W	ERR	1700	99.0	100.0	All	Missing data (Y12 network error?)
Tower Y	ERR	1700	99.0	100.0	All	Missing data (Y12 network error?)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thundershowers in area 1300-1500 hrs

Wednesday, April 28, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status T	ime Range		Recovered 60-min	Sensors A	ffected	Comments
Tower A	OK		100.0	100.0			
Tower B	OK		100.0	100.0			
Tower C	OK		100.0	100.0			
Tower K	OK		100.0	100.0			
Tower L	OK		100.0	100.0			
Tower M	OK		100.0	100.0			
Tower W	OK		100.0	100.0			
Tower Y	OK		100.0	100.0			

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Thursday, April 29, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308

Email birdwellkr@ornl.gov, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		T1 line installed at site by Verizon Wireless
Tower W	OK		100.0 100.0		
Tower Y	OK		100.0 100.0		

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair

None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes

Friday, April 30, 2010

Compiled by KR Birdwell, MS6418, CSM/CSED, ORNL, Phone 865.576.2308 Email <u>birdwellkr@ornl.gov</u>, Pager 865.873.7149

SITE STATUS (Instrumentation, 15-Minute Data Collection)

Site Name	Status	Time Range	% Data Recovered	d Sensors Affected	Comments
			15-min 60-min		
Tower A	OK		100.0 100.0		
Tower B	OK		100.0 100.0		
Tower C	OK		100.0 100.0		
Tower K	OK		100.0 100.0		
Tower L	OK		100.0 100.0		
Tower M	OK		100.0 100.0		T1 line communications set up by DA Fye
					Normal communications restored to Tower M
					at 1400 hrs.
Tower W	ERR	0615, 2130	98.0 100.0	All	Missing data (Y12 network error)
Tower Y	ERR	0615, 2130	98.0 100.0	All	Missing data (Y12 network error)

NETWORK INTERRUPTIONS

Affected Systems Time Range %Data Recovered Cause/Repair None

Special Notes

Wind speed threshold is 0.5 mph on all sites unless otherwise noted.

Weather Notes